



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Thursday, May 18, 2017

Inspector

Default Inspector

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION :

Property Occupied : No	Temperature : 68 F
Estimated Age Of Property : 16 Year(s)	Weather :
Property Faces : <input type="checkbox"/> North <input type="checkbox"/> South <input checked="" type="checkbox"/> East <input type="checkbox"/> West	<input checked="" type="checkbox"/> Fair
Type of Property :	Soil Conditions :
<input checked="" type="checkbox"/> Commercial <input checked="" type="checkbox"/> Single-Family	<input checked="" type="checkbox"/> Dry
Primary Construction :	Persons Present :
<input checked="" type="checkbox"/> Block	

DEFINITIONS :

Below are listed the definitions used throughout the report to describe each feature of the property.

G (GOOD)	Average to above-average condition for the building system evaluated, taking into consideration factors of age and design. Generally, other than normal maintenance, no repair is recommended or required.
F (FAIR)	Average condition for the building system evaluated, taking into consideration factors of age and design. Some short term or immediate maintenance or repairs are recommended to return the system to a good condition.
P (POOR)	Below-average condition for the building system evaluated, taking into consideration factors of age and design. Immediate repair, significant work or replacement is anticipated to return the building system to a good or fair condition.
NI (NOT INSPECTED)	The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal conditions and no representations of whether or not it was functioning as intended were made.
NA (NOT APPLICABLE)	This item is not applicable or not present

SCOPE OF THE INSPECTION :

The intent of the property inspection is to identify and communicate conditions of the facility and components of the facility that are categorized and listed on the inspection form, particularly maintenance issues. The inspection is a visual review of readily accessible areas and components. The inspector will endeavor to observe the operation of mechanical and electrical systems and note the condition of the systems. It is not technically exhaustive and no excavation, disassembly or removal of covers, panels or obstructions is performed. Hidden or obstructed defects may not be observed.

Inspection Date: 05/18/2017
Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

GRADING / DRAINAGE

☒ Monitor Condition

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Near Level

Comments:

There exists a good slope for drainage away from the foundation. Movement and settling of the concrete sidewalks and curbing should be monitored to ensure that drainage away from the foundation is maintained. Monitor cracking and settling of pavement in the parking lot. Repair larger open cracks as needed.



South side of property. Adjacent property is at a higher elevation.



Catch basins on the property take rainwater from the roof through downspouts and underground into the catch basins.



South side of property. Adjacent property is at a higher elevation.



South side of property slopes to the west to a drainage area and catch basins.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

PARKING LOT

☒ Monitor Condition

G	F	P	NI	NA
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Asphalt

☒ Cracks

Comments:

The driveway and parking areas for this property are part of a larger development and all of the parking and driveway areas are in a similar condition. Settlement has occurred and the asphalt, although patched in the past, will need routine maintenance to remain viable.

Parking lot needs to be inspected and maintained routinely as there are large cracks, (previously filled), that have reopened. Consider sealcoating of the lot after cracks have been repaired and filled.



Parking lot cracks



Entrance to driveway area at the southeast corner.



Larger crack on the east side drive area.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

FLATWORKS/SIDEWALKS

☒ Monitor Condition
☒ Recommend Repairs

G	F	P	NI	NA
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Concrete

☒ Cracks/Settlement

Comments:


The sidewalk on the east side of the building has separated from the foundation by 1.5". There is evidence of settlement of the concrete flatwork as uplifted sections and corners have been "ground" down to eliminate tripping hazards and try to make them more level. Make repairs as needed and continue to monitor for movement.



Sidewalk area that has been ground down to eliminate a tripping hazard.



Sidewalk at front of store showing signs of settlement. Has edges ground down.



East side of building showing opening at foundation.



Sidewalk has pulled away 1.5" on the east side of the building.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

FENCES / ENCLOSURES

☒ Recommend Repairs

G	F	P	NI	NA
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Chain Link

☒ Masonry

☒ General Deterioration

☒ Need Repairs

☒ Portion(s) Missing

Comments:

Dock area retaining wall top cap is damaged in at least three places and water can get in under the cap. The railing anchor bolts on this wall are rusting and are at risk of failing.



Truck dock area.



Fenced area for recycling compactor.



Rusted bolted connection of railing on top of loading dock wall.



Top cap is damaged on the loading dock retaining wall.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

RETAINING WALLS/LANDSCAPING

☒ Recommend Repairs

G	F	P	NI	NA
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Driveway

☒ Block

☒ General Deterioration

Comments:

Repair grass areas that have died due to "drive over" at curb as well as repair retaining wall top cap where damaged.



Top cap is damaged on the loading dock retaining wall.



Retaining wall damaged top cap and block mortar joints in need of painting.



Dock area retaining wall.



Curbing at southeast driveway. Note the 'drive over' area of dead grass.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

ROOFING

G	F	P	NI	NA
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Age: <2 Year(s)

Design Life: 25-30 Year(s)

Layers: 1

100% Visible

☒ Walked On

☒ Membrane

Comments:

The roof was replaced last summer and a membrane roof was installed. Some small areas of ponding as evidenced by settled and dried dirt areas were seen. In a few locations where water and dirt have puddled on the roof, ensure that no seams are open to create any leaking.

Leaks not always detectable.



Membrane flashing at parapet wall.



Dirt has settled in the ponding area.



View across the north face looking east.



North side galvanized top cap flashing that is showing signs of rust.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

FLASHING/VALLEYS

☒ Monitor Condition

G	F	P	NI	NA
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Composition / Membrane

☒ Metal

Comments:

Repair open caulk joint on vent pipe that had been previously caulked.



Open hole in caulking at vent pipe.



Roof service completion date of October 2013 and parapet wall top cap.



Membrane roof joint. Typical, in good condition.



Typical roof penetrations.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

ROOF DRAINAGE SYSTEM

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Aluminum

Comments:

The storm water run off is handled through the sheeting action of the roof. The water runs towards the south side of the roof and is caught into a gutter and series of downspouts that direct the water underground and into a storm water catch basin system.



View of the roof's south edge looking west. Gutter is to the left side.



Area of ponding on the roof.



Parapet wall looking east - gutter to the right side of photo.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

PARAPET WALL

☒ Concrete Block

	G	F	P	NI	NA
EXTERIOR FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
CAP FLASHING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
COVING/FLASHING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
SCUPPERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments:

The parapet wall was in good condition with the exception of the top cap at the front of the building which is showing signs of rust.



Parapet wall looking north along the west side next to adjacent roof area to another store.



Parapet walls in northeast corner of roof.



Hatchway into larger and higher parapet section.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

EXTERIOR SURFACE

☒ Concrete Block

☒ Cracked

☒ Needs Caulk / Seal

☒ Needs Paint

	G	F	P	NI	NA
SIDING/TRIM	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
EXTERIOR FAUCETS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
EXTERIOR ELECTRICAL OUTLETS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

The decorative concrete block at the north and east sides of the building have some areas of cracking due to settling. Seal cracks and make repairs as necessary and monitor for any further movement. Where block mortar joints have cracked and been filled, the repairs are very visible and the wall is in need of painting.



Block wall with visible joints.



Block wall with visible joints.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999




Deteriorated concrete block face.




Concrete block vertical crack with rust.




Vertical crack in concrete block at corner.



Vertical crack in wall.



Vertical crack in wall.



Vertical crack in wall extending all the way to the top of the parapet wall where the block has broken.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

EXTTERIOR LIGHTING

EXTERIOR LIGHTING

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

The exterior lighting consists of wall mounted light fixtures on all four sides of the building as well as pole mounted lighting supporting the parking lot and driveways.



Wall mounted lighting at the front of the building.



Pole mounted lighting in the parking lot.



Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

EXTERIOR SIGNAGE

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

The exterior signage was in good condition at the time of the inspection.

FENESTRATION SYSTEMS

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Metal

☒ Aluminum

☒ Insulated Pane(s)

Comments:

The only windows are located at the front entrance door. They are in good condition.



View of windows from the inside of the building.

MAIN DOORS

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Metal

Comments:

The main doors and service doors are in good condition. There are a few signs of rust on the hollow metal exterior service doors that will need some maintenance.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Main service door at shipping and receiving area.



Exterior service door - note spot of rust at top of door.



Service door with scratch in the bottom of door and a small spot of rust at base of frame.

FREIGHT DOORS

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Dock area - service doors.



Rust at bottom of service door.



Dock area freight overhead door.

OVERHEAD DOORS

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Metal

Comments:

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

EXTERIOR FOUNDATION

G	F	P	NI	NA
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Concrete Block

☒ Slab

☒ Limited Observation

Comments:

Along the base of the foundation where the sidewalk areas come into contact with the exterior walls, there is the need to reseal these joints. They have been filled in the past but have opened up again.



Movement of sidewalks at foundation.



Open joint at foundation wall.



Open joint at foundation wall.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

Attic / Roof

ATTIC FRAMING/SHEATHING

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Plywood / Panel Board / OSB ☒ Steel Joists

Comments:

The roof structure is in good condition. The higher parapet wall is framed with metal studs and plywood.

Leaks not always detectable.



Framing of front parapet wall - metal studs and plywood.



Framing of front parapet wall - metal studs and plywood.

ATTIC INSULATION

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Limited visibility, but new membrane roof has insulation installed under membrane.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



General view of roof at corner.



Backside of main parapet wall at north side.



General view of roof looking south.



General view of roof looking north.

Interior Foundation

☒ Slab On Grade

STRUCTURAL FRAME AND BUILDING ENVELOPE

		G	F	P	NI	NA
BEAMS	<input checked="" type="checkbox"/> Steel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
JOISTS	<input checked="" type="checkbox"/> Trusses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
POSTS	<input checked="" type="checkbox"/> Steel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PIERS	<input checked="" type="checkbox"/> Concrete	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

The structural system was in good condition at the time of inspection.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Detail of joist and decking.

FLOOR/SLAB

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☒ Concrete

☒ Obscured / Covered

Comments:

ELECTRICAL

SERVICE SIZE (Main Panel)

☒ 600 Volt

☒ 1200 AMP

	G	F	P	NI	NA
SERVICE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ENTRANCE CABLE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PANEL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
SUB-PANEL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
BRANCH CIRCUITS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
BONDING/GROUNDING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ARC FAULT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
SURGE PROTECTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FIRE ALARM SYSTEM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

The service is a 600 volt, 1200 Amp, 3 phase, 4 wire system and seems adequate for its intended purpose.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.



Electric meter located on south exterior wall near transformer.



South side transformer and meter.



Secondary electrical distribution room.



Main electrical service room with panels and main disconnect.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

PLUMBING

Water Service

☒ Water Public

Sewage Service

☒ Sewage Public

		G	F	P	NI	NA
SUPPLY	<input checked="" type="checkbox"/> Copper	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DRAINS	<input checked="" type="checkbox"/> PVC	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
VENTS	<input checked="" type="checkbox"/> PVC	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FIRE SUPPRESSION SYSTEM		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Main utility line, septic systems and gray water systems are excluded from this Inspection.



Water service meter located near the fire protection riser in closet off of retail floor.



Fire protection system at roof metal decking.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Fire protection and water service closet.



Fire protection service tags and records. All up to date.

WATER HEATER

G	F	P	NI	NA
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Brand: Unidentified
Design Life: 15-20 Year(s)

Model: Unidentified
SerialNo: Unidentified

Size: 20 Gallon(s)

Age: 15-20 Year(s)

☒ Gas

Comments:

There is an approx. 20 gallon electric water heater located in the ceiling space above the restrooms. Access to the water heater was limited in the ceiling space due to stored materials in the way of reaching the unit.



Water heater above ceiling space.



Access to water heater above ceiling space was blocked by stored materials.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

HEATING (TRANE UNITS)

Brand: Trane Model: Various Models BTUs: 0 Age: 17 Year(s)
Design Life: 20-25 Year(s) SerialNo: Unidentified

	G	F	P	NI	NA
OPERATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

There are 6 Trane RTU's that are 17 years old.

Heat Exchanger - Unable to detect cracks/holes without dismantling unit.



Trane RTU unit.

HEATING (CARRIER UNITS)

BTUs: 0 Age: 20+ Year(s)

	G	F	P	NI	NA
OPERATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

There are 6 Carrier "Weathermaker" RTU that are 20+ years old.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Smaller Carrier unit.

HEATING (STERLING UNITS)

Brand: Sterling

BTUs: 0

☒ Gas

OPERATION

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

There are 3 Sterling ceiling mounted gas-fired unit heaters located in the installation service bay and warehouse/receiving areas.

DRAFT CONTROL/VENT

☒ Metal Pipe

☒ PVC

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Ventilation pipe on roof has open caulk joint, (small opening) that needs to be filled to keep water out. RTU-7's condensate line is disconnected from the unit and should be reattached.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Gas fired unit heater ventilation through roof.



Typical roof penetrations.



Open hole in caulking at vent pipe.



RTU - 7 condensate line is disconnected from unit.

HVAC DISTRIBUTION

☒ Ductwork

	G	F	P	NI	NA
DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
BLOWER	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
CONTROLS/THERMOSTAT (CALIBRATIONS/TIMED FUNCTIONS NOT CHECKED.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
CIRCULATOR PUMP	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments:

Gas fired unit heaters distribution system is accomplished through direct fan and the roof top units distribution is facilitated through short sections of ductwork into the retail below.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Roof Top Unit and exhaust venting.



Roof Top Unit and exhaust wiring.



Roof Top Unit - Typical discharge directly into the space below with minimal distribution.

COOLING

G	F	P	NI	NA
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Brand: Trane/Carrier

Model: Various models

Age: 15-20 20-25

☒ Gas

Comments:

See comments in the Heating section regarding the RTU's.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Roof Top Unit accommodates both heating and cooling.



Roof Top Unit accommodates both heating and cooling.



Roof Top Unit accommodates both heating and cooling.



Roof Top Unit accommodates both heating and cooling.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

BATHROOMS

	G	F	P	NI	NA
CEILINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WALL(S)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FLOOR/FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR DOORS/HARDWARE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HEAT/AIR DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WATER CLOSET & FIXTURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

All restrooms were in good condition.



Men's restroom.



View of restroom entrance doors.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Women's restroom.



Women's restroom vanity.

LOBBY/ENTRANCE

	G	F	P	NI	NA
CEILINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WALLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WINDOWS/TRIM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FLOOR/FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR DOORS/HARDWARE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HEAT/AIR DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Lobby was in good condition at the time of the inspection.

GENERAL RETAIL SPACE

	G	F	P	NI	NA
CEILINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WALLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WINDOWS/TRIM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FLOOR/FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR DOORS/HARDWARE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HEAT/AIR DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999


Comments:

The general retail space was clean and organized with no signs of maintenance needed.

EMPLOYEE BREAKROOM

	G	F	P	NI	NA
CEILINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WALLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WINDOWS/TRIM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FLOOR/FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR DOORS/HARDWARE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HEAT/AIR DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:



Employee lounge and breakroom

STORAGE

	G	F	P	NI	NA
CEILINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WALLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FLOOR/FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR DOORS/HARDWARE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HEAT/AIR DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections


SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

Comments:

Storage space is provided adjacent space to the warehouse/receiving.



Storage area off of warehouse space.



Back area of display space being used for storage.



Former retail space being used for storage.

WAREHOUSE

	G	F	P	NI	NA
CEILINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
WALLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
FLOOR/FINISH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
INTERIOR DOORS/HARDWARE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
HEAT/AIR DISTRIBUTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999



Warehouse rack storage.



Warehouse meeting room.



Shipping/receiving area next to dock doors.

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email:



National Property Inspections

SAMPLE COMMERCIAL, 1234 Any Street, Anycity, US, 99999

Inspection Date:
05/18/2017

Inspector: Default Inspector
Inspector Phone:

Email: